

# INSTRUCTION MANUAL

MS-70 MX-50 MF-50 ML-50



WM+PD4000477D

# This manual and Marks

All safety messages are identified by the following, "WARNING" or "CAUTION", of ANSI Z535.4 (American National Standard Institute: Product Safety Signs and Labels). The meanings are as follows:

<b>MARNING</b>	A potentially hazardous situation which, if not avoided, could result in death or serious injury.
	A potentially hazardous situation which, if not avoided, may result in minor or moderate injury.

This is a hazard alert mark.

This mark is the IEC417 mark for "Caution. Hot surface". Do not touch parts affixed with this mark without adequate protection.



This mark informs you about the operation of the product.

- **D** This manual is subject to change without notice at any time to improve the product.
- Product specifications are subject to change without any obligation on the part of the manufacturer.
- Under the copyright laws, the instruction manual and the software (program) described in it are copyrighted, with all rights reserved.
   The software may be installed into one computer and may not be installed into other computers without the prior written consent of A&D Company. Copying includes translation into another language, reproduction, conversion, photocopy and offer or loan to another person.
- The purchaser may make one copy of the software for backup purposes.
   The manual and the software may not be copied, in whole or part, except as described above.
- Windows is a registered trademark of the Microsoft Corporation.

© 2004 A&D Company, Limited All rights reserved.

# **Contents**

1. Sat	ety and Compliance	3
2. Pre	ecautions	5
2.1.	Installing the Analyzer	5
2.2.	During Use	
2.3.	After Use and Maintaining the Analyzer	
3. Ou	tline and Features	8
4. Pa	cking List and Names of each part	10
4.1.	Display and Keys	
		12
5. Pre	parations	14
5.1.	Installing the Analyzer	14
5.2.	Setting the Clock and Calendar	15
5.2	.1. Operation	15
5.3.	Proper Operation for Precision Measurement	16
5.3	.1. Operation of the sample	16
5.3		
5.3	.3. The Glass Fiber Sheets ( of accessory)	17
6. Me	asurement Procedure	18
6.1.	Standard Mode Operation	18
6.1	.1. ACCURACY	18
6.1	.2. Operation	18
6.2.	Quick Mode Operation	21
6.2	.1. ACCURACY	21
6.2	.2. Operation	21
6.3.	Program Number	24
6.3	.1. Storing a Measurement Program to a Program Number	24
6.3	.2. Recalling a Measurement Program with a Program Number	24
7. Me	asurement Programs	25
7.1.	List of Measurement Programs	
7.1	0	
7.1	.2. Analyzing mode of the Automatic Mode	27
7.1	.3. Analyzing mode of the Timer Mode	27
7.1	.4. Drying Program (Heating Pattern and Drying Termperature)	27
7.1	5. Measurement Unit	28
7.2.	Procedures to Store a Measurement Program	29
7.2	.1. Standard Drying	29
7.2	.2. Ramp Drying	32
7.2	.3. Step Drying	36

8. Check Function	41
8.1. Self-Check Function	41
8.1.1. Operation	41
8.2. Test Sample (Sodium Tartrate Dihydrate)	42
9. Connecting to a Printer	10
<ol> <li>9. Connecting to a Printer</li> <li>9.1. Print samples</li> </ol>	
9.1. Print Samples 9.1.1. Example To Print The Whole Data At One Time	
9.1.2. Example To Print Selected Items	
9.1.3. Explanation for Print Item	
10. Connecting to a Computer	
10.1. RS-232C Serial Interface	50
10.2. Output Format	51
10.3. Command	52
11. Data Memory Function	53
11.1.1. Preparation	
11.1.2. Output All Data at One Time	
11.1.3. Delete All Data at One Time	
12. Calibration	
12.1. Identification Number (ID No.)	
12.1.1. Setting the ID Number	
12.2. Calibration of the Weighting Sensor	
12.2.1. Operation	
12.3. Calibration of Drying Temperature (for MS-70 and MX-50)	
12.3.1. Operation	
13. Function Table	60
13.1.1. Operation	61
	( )
14. Maintenance	
14.1. Cleaning the Heater Unit	
14.2. Replacement of the Halogen Lamp	
14.3. Factory Settings	
14.3.1. Operation	
14.4. Troubleshooting	
14.5. Error Message	
15. Specifications	67
15.1. Dimensions	68
15.2. Accessories and Peripheral Equipment	
16. Index	

# 2. Safety and Compliance

### 

- Do not use a sample that could make a dangerous chemical reaction and cause an explosion or poisonous gas, when the sample is dried.
- Keep flammables away from the analyzer.
   Parts of the analyzer become very hot. Materials placed near it might catch fire.
- Do not use the analyzer in ambient ignitable gas. It may cause explosion and fire.
- Use a power source (voltage, frequency, outlet type) adapted to the specification of the analyzer. If excessive voltage is used, the analyzer may overheat and be damage or cause a fire.
- Turn off the power switch and remove the power cord from the power outlet, when replacing the halogen lamp. Touching an electrode of the halogen lamp connector carelessly, it may cause to receive an electric shock.
- Do not disassemble the analyzer. It may cause an error, damage, receiving an electric shock or fire. If the analyzer needs service or repair, contact the local A&D dealer.
- Avoid getting the analyzer wet. It is not a water-resistant structure. If there is leakage of liquid into the analyzer, it may cause damage to the analyzer or receiving electric shock.
- Do not look at the active halogen lamp to protect your eyes from damage.
- Do not drop, hit or crack the glassware including the halogen lamp, to avoid an injury.
- When the halogen lamp is used beyond 5000 hours, we recommend replacing the lamp with a new one to avoid trouble.
- □ When discarding a halogen lamp, do not break it to avoid scattering glass and injury.

# 

- Do not touch the heater cover, the halogen lamp, glass-housing, pan handle, sample pan and sample without adequate protection, it could cause a burn or scald. Parts of the analyzer are very hot when a measurement finishes. For operation, use the specified grips of the heater cover and pan handle. Use the standard accessory tools.
- □ Do not touch parts affixed with the ▲ mark, because they may get very hot and dangerous.
- When the analyzer is used in a room where hot air does not diffuse, it may unexpectedly overheat. In this case, adjust the drying temperature or move the analyzer to a place with adequate ventilation.
- Avoid leaving the analyzer in direct sunlight, as that could cause discoloration of the case or a malfunction.

#### **Compliance with FCC Rules**

Please note that this device generates, uses and can radiate radio frequency energy. This device has been tested and has been found to comply with the limits of a Class A computing device pursuant to Subpart J of Part 15 of FCC rules. These rules are designed to provide reasonable protection against interference when this device is operated in a commercial environment. If this unit is operated in a residential area, it may cause some interference and under these circumstances the user would be required to take, at his own expense, whatever measures are necessary to eliminate the interference.

(FCC = Federal Communications Commission in the U.S.A.)

#### **Compliance with Council Directives**

CE This device features radio interference suppression and safety regulation in compliance with the following Council Directives Council directive 89/336/EEC EN61326 EMC directive Council directive 73/23/EEC EN61010-1 Low voltage directive Precautions

## 3.1. Installing the Analyzer

#### ---Caution for Measurement Safety ---

3.

- Do not install the analyzer in a dangerous place.
- Maintain the following ambient condition to operate the analyzer.
   5°C to 40°C (41°F to 104°F), 85%RH or less (no condensation)
- Keep flammables away from the analyzer.
- Do not put anything on the heater cover.
- Do not install the analyzer in a small airtight room. If the analyzer is used in an airtight room, hot air does not diffuse, the sample may unexpectedly overheat. In this case, the safety circuit of the halogen lamp activates. Move the analyzer to a place with adequate ventilation or adjust the drying temperature.
- There is the voltage label on the back panel of the analyzer.
   Confirm that voltage, frequency and outlet type is correct for your local voltage.
- Confirm that the rated voltage of the halogen lamp is correct for your power supply voltage. (Refer to 15.4.Troubleshooting)

Voltage Label	Power Supply Voltage	The Rated Voltage of Halogen Lamp
100 - 120 V	AC 100 V to AC 120 V	AC 120 V
200 - 240 V	AC 200V to AC 240 V	AC 240 V

- Ground the analyzer using the ground terminal of the power cord.
- Do not change the setting of the I/II switch on the rear of the analyzer. If the incorrect setting is used, it may damage the analyzer or cause a fire.

---Caution for Precision Measurement---


Confirm the following condition, because the weighing sensor (S.H.S.) is very sensitive.

- The weighing surface should be solid and free from vibration, drafts and as level as possible.
- Install the analyzer in a stable place avoiding vibration and shock.
- □ Install the analyzer where it not affected by heaters or air conditioners.
- Ensure a stable power source.
- Keep the analyzer away from equipment that generates magnetic fields.
- Discharge static electricity.

# 3.2. During Use


#### ---Caution for Measurement Safety ---

- Operate the analyzer using the following procedure.
- Put the sample pan in the correct position.
- Handle the grip of the heater cover to open and close it.
- Use the pan handle to move the sample pan.
- Do not touch hot parts around the grass-housing, when the cover is opened.
- The glass-housing is very hot. It may cause a burn, if touched.
- □ The sample pan and pan handle is very hot, when finishing measurement. Allow them cool down.
- Use the tweezers or spoon to move the sample.



#### Grips and Hot Parts.

Hot parts are as follows:
 Use the following grips to operate the analyzer.



#### Do Not Measure a Dangerous Sample.

Do not use an explosive, flammable or noxious substance as a sample.
 Do not use a sample that makes a dangerous substance by drying it.
 Do not use unknown substances.

Put correctly

- When a sample surface becomes dry first and the inner pressure increases, the sample may explode. Do not use such a sample.
- **u** Turn off the power switch if a sample catches fire.
- □ The case of the analyzer is made of a flame-retardant substance (UL94V0).

#### Do Not Put any Flammable Matter Around the Analyzer.

- During and after measurement, parts of the analyzer become very hot. Do not put flammable matter near the analyzer.
- Do not put any thing on the heater cover.

#### Caution for Heating (Drying).


- When the drying temperature is set to 200°C and measurement is started, the thermostat of the halogen lamp may work after 30 minutes. When the halogen lamp has cooled down, the next measurement can be started. If necessary, change the drying time and temperature.
- When a measurement is started and the time passes one hour, the maximum temperature is automatically regulated to 160°C for safety.

#### **Operation to Stop Measurement**

During measurement, the <u>STOP</u> key is always effective. If there is an error or danger, press the <u>STOP</u> key.

## 3.3. After Use and Maintaining the Analyzer

- □ Put dust cover on the analyzer after it is cool.
- Clean the glass-housing carefully.
- Clean fingerprints from the halogen lamp to keep its life. Refer to "15.2.Replacement of the Halogen Lamp".
- Avoid mechanical shock to the analyzer.
- Do not disassemble the analyzer.
- Protect the analyzer from excessive dust.
- Use the packing box (special container) to move the analyzer.
- Clean the analyzer with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not use organic solvents to clean the analyzer.
- Do not disassemble or remodel the analyzer.



## 4. Outline and Features

- The moisture analyzer is built using a super hybrid sensor (S.H.S.) adopted in an analytical balance. Therefore, the result is more precise and gets greater repeatability.
- An analyzer using the S.H.S. has high sensitivity, needs only a sample quantity of a few grams, and the analysis time becomes shorter.
- A 400W halogen lamp is used as the heating source and the temperature on the sample pan can reach 200°C within two minutes.
- There are five analysis modes.
   Standard mode..... The moisture content can be obtained with settings of the

  - Manual mode.......... This mode can stop the measurement by key operation and the result is decided.
- The heating patterns can be used to analysis mode without quick mode. (For ML-50, standard drying and quick drying can be used only)
   Standard drying ..... Maintains a constant drying temperature. Ramp drying...... Increases the drying temperature gently.
   Step drying ....... Uses multiple steps of the drying temperature. Quick drying ....... Heats up 200°C for few minutes and uses a constant drying temperature.
- The analyzer can store and recall proper individual settings for each sample using a program number (PROG No.).

	MS-70 / MX-50	MF-50	ML-50
Maximum program number	20 sets	10 sets	5 sets

□ The data memory function can store results and output them at one time.

Maximum number of storable results	MS-70 / MX-50	MF-50	ML-50
	100	50	30

- The software "WinCT-Moisture", the standard accessory of the MS-70 and MX-50, has a function that can make a graph of the change of moisture content in realtime and has an optimum temperature search program that judges heating at an appropriate temperature setting.
- The software "WinCT", the standard accessory of the MF-50, is communication software for transmitting data to a computer using Microsoft Windows.


- □ The analyzer is equipped with a serial interface as standard. It can be connected to a printer or computer.
- The analyzer can calibrate the weighing sensor (Use special mass.) and drying temperature (Use temperature calibrator for MS-70 and MX-50 except MF-50 and ML-50). The analyzer can output the data required at GLP, GMP and ISO at the end of the calibration.
- **□** The analyzer has a self check function that can detect function errors.
- □ The analyzer displays the current change of moisture content per one minute [%/ min] in real-time. It can be used for the reference to find the analyzing mode.
- The sample pans included in the standard accessory can be used repeatedly.
- There is a test sample that is used to check the moisture accuracy. (The test sample is a part of standard accessory except ML-50)
- The glass fiber sheets can be used to quick and precision measurement for liquid sample. (The glass fiber sheets are a part of standard accessory except ML-50)
- A reference card is built into the bottom of the analyzer.

#### Principle and Use


The moisture analyzer, based on the principle of thermogravimetric analysis, dries a sample using a halogen lamp and obtains the moisture content in % and other results by the difference between the wet weight and dry weight.

# 5. Packing List and Names of each part

- Keep the packing box to move the analyzer.
- Packing list as follows:



#### All Accessories



# ▲ Caution

Please confirm that the analyzer is correct for your local voltage, receptacle type and power cord.

#### #1 Differences of Accessory

	MS-70 MX-50 MF-50		ML-50
Dust cover			
Test sample			Not included.
Glass fiber sheets	Inclu	ded.	
Spoon			They can be purchased by
Tweezers			your order.
RS-232C serial interface cable			your order.
CD-ROM	WinCT-Moisture WinCT		
Sample pan	20		10
Pan handle	2		1

#### 5.1. Display and Keys 4 6 7 5 3 8 8.8.8.8.8.8.8.8.8 % Mg RATIS <sup>SET</sup>☐ ☐ ☐ ☐ ○ ☐ ☐ ☐ ☐ ○C 2 9 ↓ 1 1 1 1 sec ↓ 1 1 1 . 1 min HEATING PATTERN 1 10 #2 Name State and Meaning At gram display Preset time is displayed at timer mode 1 Time At measurement Analysis time At gram display Set temperature of sample pan Temperature of 2 At measurement Current temperature of sample pan sample pan PROG: Program No. At gram display Program number of measurement program Data No. Storing data Data number of data memory function 3 MEM: Analysis mode At setting Symbols: 5td, quc, U-a, U-t, U-m At gram display Sample quantity [g] 4 Value At measurement Current moisture content [%] 5 Accuracy indicator of measurement Accuracy **Operation indicator** Indicator of heater cover, sample and drying process Sample needs at least 0.1 g or more to start measurement. Lights when heater cover is closed 6 111 Blinks during measurement. Disappears when not measuring Sample mark: Lights when the sample is 0.1 g or more. Reference of sample quantity Proper sample for standard mode and quick quantity range 7 Level indicator mode. Standard mode At gram Target quantity of sample [g] Target quantity Quick mode 8 display Preset termination value [%/min.] Automatic mode Current drying rate [%/min.] At measurement Drying rate Measurement unit <u>W-D</u> x100 % MOIST Moisture content Ŵ is based on W W <u>W - D</u> x100 MOIST Moisture content (Atro) % W: Wet sample mass is based on D /D D % MOIST D 9 x100 D: Dried sample mass Dry content D/W W % MOIST W - x100 Ratio W/D D Gram value g Heating pattern #1 Standard drying Maintains a constant Drying temperature drying temperature. Ramp drying Increases the drying 10 Drying temperature temperature gently. Uses multiple steps of Step drying Drying temperature the drying temperature. Quick drying 200°C Quick mode approx. 3min. Drying temperature


- #1 ML-50 can select "standard drying " and "quick drying" only.#2 ML-50 does not display "heating pattern".

Analysis mode	Symbols ( during settings)	Gram display (after settings and before measurement)		
Standard mode	5td			
Quick mode	quc			
Automatic mode	U-a	Image: second		
Timer mode	U-t	$\begin{array}{c c} & & & & \\ & & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & & \\ & & & \\ & & & &$		
Manual mode	U-m	<sup>xxx</sup> 4 <b>y</b> xx 105 % <b>5.000</b> g		


#### **Display Samples for Analysis Mode**

#### Key Operation and Key Functions

Keys		Function and action
PROGRAM	PROGRAM	Stores or recalls measurement program with the program number during the gram display.
		Selects a heating pattern while the drying temperature is selected.
SELECT	SELECT	Selects item in the measurement program.
€,♠	↓ , ↑	Changes value of item in the measurement program.
ENTER ENTER		Stores current condition in the measurement program number. Output data at measurement.
START	START	Start prepared measurement Sample needs at least 0.1 g or more to start measurement.
бтор	STOP	Stop current measurement
RESET	RESET	Sets the display to zero in the unit of gram. Cancel key.



- 7. Install the pan support. Align together the  $\Delta$  signs on the pan support and body.
- Put the sample pan on the pan handle.
   And hook the pan handle on the notch in the rim of the breeze break ring.



# 6.2. Setting the Clock and Calendar

Adjust the built-in clock and calendar before use.

#### 6.2.1. Operation

- 1. Turn on the analyzer. The gram unit (of weighing mode) is displayed.
- 2. Press and hold the SELECT key to display CI adj.
- 3. Press the ENTER key to display the calendar. Example: 15th April, 2002
- To skip the calendar settings.
   Press the or key to proceed step 5.
   To adjust the calendar settings.

Press <u>SELECT</u> key. Adjust the calendar using the following keys.

 SELECT
 key .....
 Selects a figure.

 ↓, ↑ key ......
 Selects a value for the figure.


 ENTER
 key ......
 Stores the current date and proceeds to step 5.

 RESET
 key......
 Cancels the adjustment and proceeds to step 5.


Symbols and arrangement of the calendar


ymd ......Year, month, day
mdy ......Month, day, year
dmy ......Day, month, year
The arrangement of the calendar is used for the report
of GLP, GMP and ISO.

- 5. Time is displayed.
- 6. To finish the adjustment. Press the <u>RESET</u> key to proceed step 7.
  To adjust the clock. Press the <u>SELECT</u> key. Adjust the clock using the following keys.
  <u>SELECT</u> key..... Selects a figure.
  <u>U</u>, ↑ key ...... Selects a value for the figure. ENTER key ..... Stores time and proceeds to step 7.



7. When finishing the adjustment, <u>dp</u> is displayed. Press the <u>RESET</u> key to return to the weighing mode.





## 6.3. Proper Operation for Precision Measurement

#### Operation of the sample 6.3.1.

□ Use a proper sample quantity. If the quantity is small, precise results may not be possible.


□ If the moisture content of the sample (example: plastic) can be estimated that is less than 1%, the mass of moisture is not enough for the measurement, when measuring light sample, the result may not be accurate. Consider the following sample mass for the measurement.

An estimate of moisture content	1%	0.5%	0.1%
Necessary mass for measurement	2 g at least	5 g at least	20 g at least

- If the measurement is repeated, maintain the same sample quantity.
- Crush grain samples to a small, uniform powder for a quick drying process.
- Spread the sample as evenly as possible.
- The analyzer is designed to measure the moisture content of the sample by its weight change. If the sample includes volatile matter, it may vaporize during drying causing a measurement error.
- When measuring a liquid or liquid state sample that may make a film on the surface, we recommend you use a glass fiber sheet (AX-MX-32-2).


#### 6.3.2. Operation of the analyzer


- □ Press the RESET key to display the zero value before each measurement.
- Check that the displayed sample weight is stable before measurement. Press the START key to start a measurement.
- Select the proper Analysis Mode to finish a measurement. Use the change of moisture content per one minute [%/min] that is displayed during measurement as a reference value.



- samples repeatedly or continuously, the first result is always different from the others. □ The pre-heating process is as follows: Put a sample pan, instead of a sample, on the pan. Press the START key to heat it. The analyzer temperature becomes equilibrium.
- □ Use a sample on the sample pan that has cooled to room temperature. When a sample is put on a hot sample pan, the moisture content is diffused before measurement, and precise results are not possible. We recommend you use multiple sample pans.
- Do not pile up sample pans during a measurement.
- □ Avoid drift and vibration of air conditioners. It may cause "measurement error" and "unstable value". In particular, because MS-70 is sensitive instrument, it is necessary to consider these influences.
- When the difference between ambient temperature and sample temperature is small, it may cause temperature control error. Example: If the heating temperature is set to 50°C, it is affected by an room temperature.
- Check the activation of the halogen lamp with the operation indicator. Example: If low heating temperature is set, the brightness of halogen lamp becomes dark.

•	
Check the activation with blinking	
with blinking	






16

#### 6.3.3. The Glass Fiber Sheets

Use the glass fiber sheet to measure the moisture content that is included in the following samples. When this sheet is used, vaporization of moisture is speeded up and moisture measurement result becomes quick and precise.



- This accessory is inclued in the packing for MS-70, MX-50 and MF-50.
- Purchase this accessory by your order for ML-50.
- □ Use the glass fiber sheet (AX-MX32-1) for high surface tension liquid sample.

#### Example 1 : "Liquid Sample" Or "Meltable Sample"


When the glass fiber sheet is used for these measurements, moisture is more apt to vaporize because of expanding the surface area and space. And the glass fiber sheet has the effect of preventing a surface film from forming at drying process.

- A sample including a lot of moisture
   Milk, yogurt, soybean milk, condensed milk, ketchup, resin, liquid paste, hand soap, etc.
- A sample that melts and adheres to the sample pan. Example:Chewing gums, caramel, hony, etc.

#### Procedure (Preparation before heating)

1 Put the glass fiber sheet on the sample pan.


- 2 Press the RESET key to display zero.
- 3 Soak the sample into the glass fiber sheet or put the sample on the glass fiber sheet.
- 4 Press the START key to start the measurement.



840

#### Example 2 : "If The Sample's Surface Is Apt To Carbonize"

When the sample is covered with a glass fiber sheet, carbonization of the sample surface decreases. Therefore the measurement result becomes repeatable and precise.



# 7. Measurement Procedure7.1. Standard Mode Operation

The standard mode can obtain the moisture content with settings of ACCURACY and drying program (heating pattern, drying temperature).

#### 7.1.1. ACCURACY

ACCURACY of measurement can be set either HI, MID. or LO.

The sample quantity is automatically selected by ACCURACY.

The termination value of the analyzing mode is automatically selected by ACCURACY and minimum scale value of % display.

The analysis mode is the program to finish the measurement when a change of moisture content per one minute becomes smaller than a preset termination value. The settings are as follows: Specify an ACCURACY.

				ACCURACY	
	Model	Minimum scale	HI	MID.	LO
		0.001 %	0.01 %/min	0.02 %/min	0.05 %/min
	MS-70	0.01 %	0.02 %/min	0.05 %/min	0.10 %/min
		0.1 %	0.10 %/min	0.20 %/min	0.50 %/min
Durant	MX-50	0.01 %	0.02 %/min	0.05 %/min	0.10 %/min
Preset Termination		0.1 %	0.10 %/min	0.20 %/min	
value	MF-50	0.05 %	0.05 %/min	0.10 %/min	
		0.1 %	0.10 %/min		0.50 %/min
		1 %			
		0.1 %		0.20 %/min	
	ML-50	1 %			
S	Sample quantity		10 g	5 g	1 g
	Use			$\leftrightarrow$ Quick	measurement

#### 7.1.2. Operation


This operation explanation uses the following example of the MX-50: Refer to "8.Selection of Measurement Method" for detail.

#### Input Parameters

Analysis mode	. Standard mode
Drying temperature	
ACCURACY	
Sample quantity	. Approximately 1 g (Automatic selection)
Analysis mode	
·	


#### **Stored Parameters** (Factory Settings for the MX-50)

Heating pattern	. Standard drying (		
Measurement unit	. Moisture content is based	%	MOIST
	on a wet sample		/W
Minimum scale value of % display	.0.01 %		
Minimum scale value of gram display	.0.001 g		
Data memory function	.Not used		




#### Put a Sample on the Pan

- 8. Put the breeze break ring, pan support, pan handle and sample pan in order. (With no sample.)
- 9. Close the heater cover.
- 10. When displaying a stable value, Press the RESET key. Avoid mechanical vibration, breeze and environmental noise during measurement. If it deviates from zero display, press the RESET key.



To next page



18. If the same condition is used, proceed to step 8. If changing the condition, proceed to step 2.

The sample pans can be washed and reused. There is the Reference card on the bottom of the analyzer.

# 7.2. Quick Mode Operation

The quick mode can obtain the moisture content with settings of ACCURACY and drying temperature. Sample is heated up at 200°C for approximately three minutes so that moisture content is measured quickly.

	Heating	pattern
$\square$	leating	pattern

200°C

#### 7.2.1. ACCURACY

ACCURACY of measurement can be set either HI, MID. or LO.

The sample quantity is automatically selected by ACCURACY.

The termination value of the analysis mode is automatically selected by ACCURACY and minimum scale value of % display.

Analysis mode is the program to finish the measurement when a change of moisture content per one minute becomes smaller than a preset termination value.

The settings are as follows: Specify an ACCURACY.

		ACCURACY				
	Model	Minimum scale	HI	MID.	LO	
		0.001 %	0.02 %/min	0.05 %/min	0.05 %/min	
	MS-70	0.01 %	0.05 %/min	0.10 %/min	0.20 %/min	
		0.1 %	0.10 %/min	0.20 %/min	0.50 %/min	
Descat	MX-50	0.01 %	0.05 %/min	0.10 %/min	0.20 %/min	
Preset Termination	WIX-50	0.1 %	0.10 %/min	0.20 %/min	0.50 %/min	
value	0.05 %					
	MF-50	0.1 %	0.10 %/min	0.20 %/min	0.50 %/min	
		1 %				
	ML-50	0.1 %	0.20 %/min	0.50 %/min	1.00 %/min	
	IVIL-50	1 %	0.20 /0/11111	0.50 ////////	1.00 /0/11111	
S	Sample quantity		5 g	2 g	1 g	
Use		Precise result	$\leftrightarrow$ Quick	measurement		


#### 7.2.2. Operation

This operation explanation uses the following example of the MX-50 : Refer to "8.Selection of Measurement Method" for detail.


#### Input Parameters

Analysis mode	Quick mode	
Heating pattern	Quick drying ( , Automati	ic selection)
Drying temperature	130 °C	-
ACCURACY	LO	
Sample quantity	Approximately 1 g (Automatic	c selection)
Analyzing mode	0.20 %/min (Automatic selec	tion)
Stored Parameters (Factory Settings for	or the MX-50)	
Measurement unit	Moisture content is based	% MOIST
	on a wet sample	/W
Minimum scale value of % display	0.01 %	
Minimum scale value of gram display.	0.001 g	


Data memory function......Not used



- 9. Close the heater cover.
- 10. When displaying a stable value, Press the <u>RESET</u> key. Avoid mechanical vibration, breeze and environmental noise during measurement. If it deviates from zero display, press the <u>RESET</u> key.



To next page



The sample pans can be washed and reused. There is the Reference card on the bottom of the analyzer.


# 7.3. Program Number

The measurement conditions of all program numbers are set to the standard mode at the factory. The analyzer can store and recall proper individual settings for each sample with the program number (PROG No.).

MS-70 / MX-50	20 sets	PROG 1 to 20
MF-50	10 sets	PROG 1 to 10
ML-50	5 sets	PROG 1 to 5

The same measurement program is stored in all program numbers with factory settings. Analysis mode.....Standard mode

Heating pattern.....Standard drying



# Caution If the data memory function is active, the data memory number (MEM) is displayed, in place of the program number (PROG).

#### 7.3.1. Storing a Measurement Program to a Program Number


Displaying or recalling a PROG number, a measurement program can be renewed.

PROG "1 0000g 1. Press and hold the **PROGRAM** key in gram display. PROGRAM Program number 2. Press the  $\square$  or  $\square$  key to select a program number -PROG 2 3. Press the ENTER key to use the selected number. ENTER end PROG 2 0000g 4. Press the SELECT key to edit the parameters. SELECT 5. Edit parameters of a measurement program. Edit measurement Refer to "8.Selection of Measurement Method" program. ENTER 6. Press the following key to return to the gram display. ENTER | key ..... Stores parameters to the selected number. RESET key ..... Cancels the operation and returns to the end weighing mode. PROG 2 0000a

#### 7.3.2. Recalling a Measurement Program with a Program Number

Stored measurement programs can be recalled with a program number.

- 1. Press and hold the **PROGRAM** key in the gram display.
- 2. Press the  $\blacksquare$  or  $\bigcirc$  key to select a program number
- 3. Press the ENTER key to use the selected number.



8.

# Measurement Programs

8.1. List of Measurement Programs

#### There are five analysis modes.

	Measurement Programs					
		Drying Program				
	Analyzing mode to Finish Measurement	Heating p	pattern	Drying		
	Medodrement	MS-70, MX-50, MF-50	ML-50	Temperature		
Standard Mode 5td	Measurement condition is automatically selected by ACCURACY and minimum	Standard drying Ramp drying Step drying	Standard drying			
Quick Mode quc	value of % display. When drying rate is less than preset termination value, measurement is completed automatically.	Quick d	50°C			
Automatic Mode U-a	When drying rate is less than preset termination value, measurement is completed automatically.	Standard drying	Standard	to 200°C		
Timer Mode U-t	Sample is dried for a preset time. 1min. to 480min.	Ramp drying Step drying	drying			
Manual Mode U-m	Measurement is completed by the <u>STOP</u> key. Max. 480 min.					

Drying rate: Change of moisture content per one minute [%/min]

#### 8.1.1. ACCURACY of the Standard Mode and Quick Mode

ACCURACY of measurement can be set either [H], MID. or [LO].

The sample quantity is automatically selected by ACCURACY.

The termination value of the analyzing mode is automatically selected by ACCURACY and minimum scale value of % display.

The analyzing mode is the program to finish the measurement when a change of moisture content per one minute becomes smaller than a preset termination value.

The settings are as follows: Specify an ACCURACY.

Drying rate: Change of moisture content per one minute [%/min]

#### Standard Mode

		ACCURACY			
	Model	Minimum scale	HI	MID.	LO
		0.001 %	0.01 %/min	0.02 %/min	0.05 %/min
	MS-70	0.01 %	0.02 %/min	0.05 %/min	0.10 %/min
		0.1 %	0.10 %/min	0.20 %/min	0.50 %/min
Dueset	MX-50	0.01 %	0.02 %/min	0.05 %/min	0.10 %/min
Preset Termination	1017-20	0.1 %	0.10 %/min	0.20 %/min	
value		0.05 %	0.05 %/min	0.10 %/min	
	MF-50	0.1 %			0.50 %/min
		1 %	0.40.0//	0.00.0//min	0.50 /0/11
	ML-50	0.1 %	0.10 %/min	0.20 %/min	
	IVIL-50	1 %			
S	ample qu	antity	10 g	5 g	1 g
Use		Precise result	$\leftrightarrow$ Quick	measurement	

#### Quick Mode

		ACCURACY			
	Model	Minimum scale	HI	MID.	LO
		0.001 %	0.02 %/min	0.05 %/min	0.05 %/min
	MS-70	0.01 %	0.05 %/min	0.10 %/min	0.20 %/min
		0.1 %	0.10 %/min	0.20 %/min	0.50 %/min
Durat	MX-50	0.01 %	0.05 %/min	0.10 %/min	0.20 %/min
Preset Termination	1017-20	0.1 %	0.10 %/min	0.20 %/min	0.50 %/min
value	MF-50	0.05 % 0.1 % 1 %	0.10 %/min	0.20 %/min	0.50 %/min
	ML-50	0.1 %	0.20 %/min	0.50 %/min	1.00 %/min
S	ample qu	antity	5 g	2 g	1 g
		Precise result	$\leftrightarrow$ Quick	measurement	

#### 8.1.2. Analyzing mode of the Automatic Mode

When the change of moisture content per one minute is less than the preset value, the measurement is automatically completed.

Preset Termination	Range							
value to complete measurement	MS-70		MX-50		MF-50		ML-50	
2.00 %/min			4		·			
1.00 %/min								
0.50 %/min					Avai	able	Avai	able
0.20 %/min			Avai	lable	rar	ige	ran	ge
0.10 %/min	Avai	lable	rar	ige	(Factory	setting)	(Factory	setting)
0.05 %/min	rar	nge	(Factory	setting)				7
0.02 %/min	(Factor	y setting)			· ·	7		
0.01 %/min								
0.005 %/min				,				
0.002 %/min								
0.001 %/min		7	Unavailable item					


#### 8.1.3. Analyzing mode of the Timer Mode


Sample is dried for a preset analysis time.					
Drying Time	1 minute to 480 minutes.				
Setting interval :	1 minute during 1 minute to 60 minutes.				
	5 minutes during 60 minutes to 480 minutes.				
Factory setting:	10 minutes.				

### 8.1.4. Drying Program (Heating Pattern and Drying Termperature)

Heating pattern	l		
	Standard Mode, Automatic Mode, Manual Mode	Timer Mode	Quick Mode
Standard drying	Temperature	Temperature Time	—
Ramp drying	Temperature 50°C → Time →	50°CTime2	_
Step drying	Temperature2 Temperature1	Temperature2 Temperature1 ↑ Time1 → Time2 Stage 1 Stage 2	
Quick drying			200°C 3 min. ↑Temperature

"Temperature 1" can be set higher than "temperature 2" in step drying. ML-50, can select standard drying and quick drying only, does not display heating pattern.





#### Drying Temperature at the Sample Pan

#### 8.1.5. Measurement Unit

Unit		Formula	Display
Moisture content is based on wet sample mass	*1	<u>W - D</u> x 100 W	% MOIST /W
Moisture content (Atro) is based on dried sample mass		<u>W - D</u> x 100 D	% MOIST /D
Dry content		— <u>D</u> x 100 W	% RATIO D/W
Ratio	*2	<u>     W                               </u>	% RATIO W/D
Gram value			g

W: Wet sample mass D: Dried sample mass

\*1: Factory settings

\*2: When result reaches to 999%, measurement is stopped.


# 8.2. Procedures to Store a Measurement Program

#### 8.2.1. Standard Drying

This explanation uses the following parameters and sample displays of MX-50.

Drying temperature	Drying temperature			
Standard Mode, Automatic Mode, Manual Mode	Timer Mode			
Common Items				
Program number	ndard drying(「 ̄ ̄)) )°C isture content <mark>% MOIST</mark> 1 %			
Sample quantity App Data memory function Not	proximately 5 g			
Items for Standard Mode Analysis mode				
Items for Automatic Mode Analysis mode Aut Analyzing mode to finish measurement0.0				
Items for Timer Mode Analysis mode Timer mode (Symbol: U-t) Analyzing mode to finish measurement				
Items for Manual Mode Analysis mode Ma	nual mode (Symbol: U-m)			
1. Display the gram unit (of the weighing mode).	PROG 1 0000g			
Select a Program Number to Edit the Measurement 2. Press the PROGRAM key and press the I or they to select a program number.	t Program			
3. Press the ENTER key to use the number.	Program number			
<ol> <li>The analyzer displays end and returns to the weighing mode.</li> </ol>	PROG <sup>1</sup> 2			
Caution If the data memory function is active, the data memory number (MEM) is displayed in plac program number (PROG).				

#### Select an Analysis Mode



SELECT


#### Set the Minimum Scale Value of the Gram Display

 Select gram display with the SELECT key. Select 0.001 [g] with the □ or ↑ key.

#### Store the Parameters and Finish the Operation

14. Press the ENTER key to store the new parameters for the measurement program to program number 2. Pressing the key, the weighing mode is automatically displayed. When PROG 2 is recalled, the settings can be used.


To cancel the new parameters and return to the weighing mode, press the RESET key.



#### Standard Mode, Automatic Mode or Manual Mode


Refer to page 34 for Timer Mode

This explanation uses the following parameters and sample displays of MX-50.
50°C Final drying temperature
Common Items Program number
Items for Standard Mode Analysis mode
Items for Automatic Mode Analysis mode Analyzing mode to finish measurement0.05 %/min
Items for Manual Mode Analysis mode
1. Display gram unit (of the weighing mode).
Select a Program Number to Edit the Measurement Program 2. Press the PROGRAM key and press the I or the key to select a program number.
3. Press the ENTER key to use the number.
4. The analyzer displays end and returns to the weighing mode.
aution If the data memory function is active, the data memory number (MEM) is displayed in place of the program number (PROG).



#### Store Parameters and Finish the Operation

Press the ENTER key to store the new parameters of the measurement program to program number 3.
 Pressing the key, the weighing mode is automatically displayed.
 When PROG 3 is recalled, the settings can be used.




To cancel the new parameters and return to the weighing mode, press the **RESET** key.

#### Timer Mode

Refer to page 32 for Standard Mode, Automatic Mode or Manual Mode


This explanation uses the following parameters and sample displays of MX-50.



#### Common Items

•	·	( )	pol: U-t)
	Heating pattern Final drying temperature	Ramp drying ( 🦳	
	Ramp time Drying time	5.0 minutes	
Minimum scale v Minimum scale v Sample quantity	ralue during measurement. value of gram display	Moisture content . 0.01 % . 0.001 g . Approximately 5 g	% MOIST /W

1. D	splay gram unit (of the weighing mode).	PROG 1 0000g
2. P ↑	t a Program Number to Edit the Measurement Program ress the PROGRAM key and press the U or key to select a program number. Program num ress the ENTER key to use the number.	ber (
4. T	ne analyzer displays end and returns to the eighing mode.	PROG <sup>1</sup> 4
Caution		end PROG 4 0000g





## Standard Mode, Automatic Mode or Manual Mode

Refer to page 38 for Timer Mode

This explanation uses the following parameters and sample displays of MX-50.

		•	
	Drying temperature	e2	
	Drying temperature 1		
	Time		
	Stage 1 Stage 2		
	"Temperature 1" can be set higher than "temperature	2" in step	drvina.
		1	
	Common Items		
	Program number5 (		
	Drying program Heating patternStep		<u> </u>
	Drying temperature 1		
	Drying temperature 2		
	Time5.0 n		MOIST
	Measurement UnitMois		nt /* Wold
	Minimum scale value during measurement 0.01		
	Minimum scale value of gram display 0.007		
	Sample quantity Appr		5 g
	Data memory function Not u	used	
	Items for Standard Mode		
	Analysis mode Stand	dard mode	(Symbol: 5td)
	ACCURACYMID.		
	Analyzing mode to finish measurementAutor		ng hy ACCURACY
	Items for Automatic Mode		
	Analysis mode Autor	matic mode	e (Symbol: U-a)
	Analyzing mode to finish measurement0.05	%/min	
	Items for Manual Mode		
	Analysis mode Manu	ial mode (	Symbol: II m
1.	1. Display gram unit (of the weighing mode).		PROG 1 0000g
Se	Select a Program Number to Edit the Measurement I	Program	L
2.	2. Press the PROGRAM key and press the U or	•	PROGRAM
	🖞 key to select a program number.		
_		Program nun	
3.	3. Press the ENTER key to use the number.		PROG 5
4.	4. The analyzer displays [end] and returns to the		
4.	weighing mode.		$\bigcirc$
0	5 6	_	end
Cauti	aution If the data memory function is active, the data		
	memory number (MEM) is displayed in place	ortne	<sup>PROG 5</sup> 0000g
	program number (PROG).		





## Timer Mode

Refer to page 36 for Standard Mode, Automatic Mode or Manual Mode

This explanation uses the following parameters and sample displays of MX-50.

[	Drying temperature 2	
Drying temperature 1 Time 1	Time 2	
Stage 1	Stage 2	

"Temperature 1" can be set higher than "temperature 2" in step drying.

#### Common Items


<u> </u>					
	Program number		6 (PRO	OG 6)	
	Analysis mode		Timer me	ode (Symł	bol: U-t)
	Drying program	Heating pattern	Step dryi	ng ( 🖵	-)
		Drying temperature 1	160°C		
		Drying temperature 2	120°C		
		Time 1	5.0 minu	tes	
		Time 2	10.0 min	utes	
	Measurement unit	t	Moisture	content	% MOIST
	Minimum scale v	alue during measuremen	0.01 %		,
	Minimum scale v	alue of the gram display.	0.001 g		
	Sample quantity.		Approxin	nately 5 g	
	Data memory fur	nction	Not used	1	
	-				

- ENTER 4. The analyzer displays end and returns to the end weighing mode. PROG 5 0000g If the data memory function is active, the data Caution memory number (MEM) is displayed in place of the program number (PROG). SELECT Select an Analysis Mode 5. Press the SELECT key to select a symbol, it Analysis mode will blink. Select U-t of the timer mode with **U**"-"t 0000g the  $\square$  or  $\square$  key. (Press these keys to select it) Set the Heating Pattern 6. Select drying temperature with the SELECT key. Step drying Select step drying - of the heating pattern 105°C with the **PROGRAM** key. **Drying Temperature 1** Set Drying Temperature 1 7. Set 120°C with the  $\square$  or  $\square$  key. "1"20°C Set Time 1 8. Select time 1 with the SELECT key. Time 1 Set 5.0 minutes with the  $\square$  or  $\square$  key. 1 5.0 min Drying Temperature 2 Set Drying Temperature 2 9. Select Drying Temperature 2 with the SELECT key. Set 160°C with the  $\square$  or  $\square$  key. 160°C Set Time 2 10. Select time 2 with the SELECT key. Time 2 Set 10.0 minutes with the  $\square$  or  $\square$  key. "10.0<sup>°</sup>min2

# Select a Program Number to Edit the Measurement Program

- 2. Press the **PROGRAM** key and press the  $\downarrow$  or to select a program number.
- 3. Press the ENTER key to use the number.

1. Display gram unit (of the weighing mode).



### Set the Measurement Unit

 Select measurement unit with the SELECT key. Select the moisture content (based on wet sample ) with the ☐ or î key.

## Set the Minimum Scale Value of the % Display

12. Select the % display with the SELECT key. Select 0.01 [%] with the □ or 1 key.


### Set the Minimum Scale Value of the Gram Display

 Select the gram display with the SELECT key. Select 0.001 [g] with the □ or 1 key.

### Store the Parameters and Finish the Operation

 Press the ENTER key to store the new parameters of the measurement program to program number 6. Pressing the key, the weighing mode is automatically displayed. When PROG 6 is recalled, the settings can be used.

To cancel the new parameters and return to the weighing mode, press the RESET key.






Use the self-check function to check whether there is an error or inaccurate result. During the check, the heater is turned on and the temperature sensor is checked.

#### Caution

Do not put flammable matter near the analyzer. Do not put anything on the heater cover.

# 9.1.1. Operation

1. Display the gram unit (of the weighing mode). 0000g 2. Press and hold the **PROGRAM** key to Press and hold display CH . CH 3. Put the breeze break ring, pan support, pan handle and sample pan in order. (Do not put Do not put sample a sample on the pan.) Close the heater cover. Preparation Press the **ENTER** to start the check. If CLOSE is displayed, the heater cover is not closed. When it is closed, the self-check function is started. ENTER Checking CH 4. The check function needs approximately one minute. Good result Good result... Displays CH pa55, sounds CH pa55 buzzer and returns to weighing mode automatically. 0000g Weighing mode Error...... The buzzer sounds and an error code is displayed. Refer to 15.5. Error Message for details.



# 9.2. Test Sample (Sodium Tartrate Dihydrate)

## ---Test sample (Sodium tartrate dihydrate, Na<sub>2</sub>C<sub>4</sub>H<sub>4</sub>O<sub>6</sub>•2H<sub>2</sub>O)---

 Sodium tartrate dihydrate is used to check the accuracy of measurement for the analyzer.

As an ideal substance on theory, sodium tartrate dihydrate includes moisture content of 15.66% in the molecule. But the moisture content may change due to conditions of storage.

- The moisture content of 15.0 to 16.0% is obtained by the method below. (Unit % is based on wet sample)
- Sodium tartrate is contained in food (example : wine). If it may irritate the eyes and nose, wash with water.
- □ The test sample can not be used repeatedly. Dispose of it as flammable matter.
- In case of MS-70 MX-50 and MF-50, test sample is included in these packing list. In case of ML-50, purchase the test sample of accessory.

#### Caution A hot sample pan may cause an error. Allow the pan to cool before the next test.


#### Measurement

1. Enter the following parameters.

	Analysis mode		Standard mode (Sy	(mbol: 5td)
	•		Standard drying (	
		Drying temperature	160°C	
	ACCURACY		MID.	
	Sample quantity.		Approximately 5 g	is selected by
			ACCURACY autom	atically.
	Measurement unit		Moisture content	% MOIST /W
2.	Pre-heating process.			$\bigcirc$
	Put a sample pan, i		, on the pan.	START

Put a sample pan, instead of a sample, on the pan. Press the <u>START</u> key to heat it. The analyzer temperature becomes equilibrium.

- 3. Press the <u>RESET</u> key to make zero display. Spread the sample as evenly as possible.
- Press the <u>START</u> key to start the measurement. The result is displayed after 8 minutes normally. If the results is between 15.0 to 16.0%, the analyzer works properly.
- 5. Press the following key to complete the measurement.
   ENTER key..... Outputs (Prints) the results.
   SELECT key .... Returns to the weighing mode.
   RESET key ..... Returns to the weighing mode and displays zero.




# 10. Connecting to a Printer

- The analyzer can be connected to a compact dot-matrix printer (AD-8121B) using the RS-232C interface. The results and record adapted to GLP, GMP and ISO can be printed.
  - GLP: Good Laboratory Practice,
  - GMP: Good Manufacture Practice,
  - ISO: International Organization for Standardization
- The statistical calculation data of the result and the graph data of the change of moisture content per one minute can be printed using the function of the AD-8121B.
- □ Use the AD-8121B accessory cable to connect them.

Use	Analyzer settings				AD-8121B
	prt	5-d	pU5e	info	settings
Result and measurement program (Excluding statistics calculation)	0,1	0	1	1,2	MODE 3 Dump printing
Result with statistical calculation	0,1	0	0,1	0	MODE 1
Trace of change of moisture content per one minute	2	0	0,1	0	MODE 2 Interval printing
Data for GLP, GMP and ISO	0,1,2	0	0	1,2	MODE 3 Dump printing

### Setting List

Refer to "14. Function Table" to detail of settings. Read the instruction manual of the printer.



Compact dot-matrix printer (AD-8121B)

# 10.1. Print samples

# 10.1.1. Example To Print The Whole Data At One Time

This example is printed items of "analyzer information", "measurement program", "measurement data" and "signature space" at one time.

### **Preparation of Parameters**

Device	Parameter	Description		
	prt 0 *1	When pressing the <b>ENTER</b> key, the result is outputted.		
	prt 1	Data is outputted after measurement automatically.		
Analyzer	5-d 0 *1	Result is outputted only.		
	pU5e 1 * <b>1</b>	Approx. two seconds interval in each line.		
	info 1	To print items at one time.		
AD-8121B	MODE 3	Dump print (Received data is printed as it is)		
14. Fosters setting				

\*1: Factory settings

### How To Print

Select a parameter to print "Measurement data". Refer to "14. Function Table"

prt O	When pressing the ENTER key, the result is outputted.
prt 1	Data is outputted after measurement automatically.

## Print Example

A & D MODEL MX-50 S/N P1234567 I D LAB-123 PROGRAM No. 1 MODE STANDARD MI D. DRYI NG STANDARD 160 C UNI T MOI ST/ W	Factory Product Serial number ID number. *2 PROG No. < Analysis mode. Refer to10.1.3 Drying program. Refer to 10.1.3 Measurement Unit	Analyzer information Measurement program
INITIAL WEIGHT 5.678 g	<pre>   Wet weight </pre>	
FINAL WEIGTH 4.567 g	<pre>} Dried weight</pre>	
RESULT MOIST/W 19.57 %	<pre></pre>	
ANALYSIS TIME 6.7min	} Analysis time	Measurement data
DATE 2004/09/30 TI ME 12: 34: 56 REMARKS	} Date. Refer to 10.1.3	
	Remarks. Refer to 10.1.3	
SI GNATURE	<b>)</b> <	) 
	Signature. Refer to 10.1.3	Signature space
	•	J

\*2: ID number can be changed. Refer to "13.1. Identification Number (ID No.)"

# 10.1.2. Example To Print Selected Items

This print example is printed multiple measurement data and a suit of items specified from "analyzer information", "measurement program" or "signature space". When the title data is the same, it is economical use.


## **Preparation of Parameters**

Device	Parameter	Description	
	prt 0 *1	When pressing the ENTER key, the result is outputted.	
	prt 1	Data is outputted after measurement automatically.	
Analyzer	5-d 0 *1	Result is outputted only.	
	pU5e 1 *1	Approx. two seconds interval in each line.	
	info 2	To print specified item.	
AD-8121B	MODE 3	Dump print (Received data is printed as it is)	
Md. Fasters actions			

\*1: Factory settings

### How To Print "Analyzer Information" and "Measurement Program"

- 1. Display the gram unit (of the weighing mode).
- 2. Press and hold the ENTER key.
- 3. Press the SELECT key to select li5t.
- 4. Press the ENTER key to print them.
- 5. Display the gram unit (of the weighing mode).




### How To Print "Measurement Data"

Select a parameter to print "Measurement data". Refer to "14. Function Table"			
prt O	When pressing the ENTER key, the result is outputted.		
prt 1	Data is outputted after measurement automatically.		

### How To Print "Signature Space"

- 1. Display the gram unit (of the weighing mode).
- 2. Press and hold the ENTER key.
- 3. Press the SELECT key to select 5 i g.
- 4. Press the ENTER key to print "signature space".
- 5. Display the gram unit (of the weighing mode).



# Print Example

A & D MODEL MX-50 S/N P1234567 I D LAB-123 PROGRAM NO. 1 MODE STANDARD MI D. DRYI NG STANDARD 160 C UNI T MOI ST/ W	<ul> <li>Factory Product Serial number ID number. *1 PROG No.</li> <li>Analysis mode. Refer to 10.1.3</li> <li>Drying program. Refer to 10.1.3 Measurement Unit</li> </ul>
I NI TI AL WEI GHT 5. 678 g FI NAL WEI GTH 4. 567 g RESULT MOI ST/ W 19. 57 % ANALYSI S TI ME 6. 7mi n DATE 2004/09/30 TI ME 12: 34: 56 REMARKS	<pre>} Wet weight } Dried weight Measurement Result Analysis time Date. Refer to 10.1.3 Remarks. Refer to 10.1.3</pre>
I NI TI AL WEI GHT 5. 791 g FI NAL WEI GTH 4. 680 g RESULT MOI ST/ W 19. 19 % ANALYSI S TI ME 7. 8mi n DATE 2004/09/30 TI ME 12: 57: 12 REMARKS	<pre>} Wet weight Dried weight Measurement Result Analysis time Date. Refer to 10.1.3 Remarks. Refer to 10.1.3</pre>
I NI TI AL WEI GHT 5. 432 g FI NAL WEI GTH 4. 321 g RESULT MOI ST/ W 20. 45 % ANALYSI S TI ME 5. 4mi n DATE 2004/09/30 TI ME 13: 24: 57 REMARKS	<pre>} Wet weight Dried weight Measurement Result Analysis time Date. Refer to 10.1.3 Remarks. Refer to 10.1.3 Signature. Refer to 10.1.3</pre>

\*1: ID number can be changed. Refer to "13.1. Identification Number (ID No.)"

# 10.1.3. Explanation for Print Item

alyzer information" and "Measurement program"				
Analysis Mode	A Part of Print and Description			
Standard mode 5td	MODE STANDARD HI HI MI D. or LO			
Quick mode quc	MODE QUI CK HI HI HI MI D. or LO			
Automatic mode U-a	MODE AUTOMATI C O. 10 %/min Mode to finish measurement			
Timer mode U-t	MODE TI MER Timer mode 20. Omi n Analysis time			
Manual mode U-m	MODE MANUAL Manual mode			

# "Analyzer information" and "Measurement program"

## "Heating pattern"

ating pattern	
Heating pattern	A Part of Print and Description
Standard drying	DRYI NG STANDARD 140 C Drying temperature
Ramp drying	DRYI NG RAMP 15. Omi n 110 C Final drying temperature Ramp time
Step drying	DRYI NG STEP 8. Omi n 180 C 95 C Drying temperature of stage 1 Drying temperature of stage 2 Time of stage 1
Quick drying	DRYI NG QUI CK 130 C Drying temperature

ML-50 can select standard drying and quick drying only.

#### "Measurement Unit"

Unit	A Part of Print	Formula	Display
Moisture content is based on wet sample mass *1	UNIT MOIST/W	<u>W – D</u> W x 100	% MOIST /W
Moisture content (Atro) is based on dried sample mass	UNI T MOI ST/ D	<u>W – D</u> D x 100	% MOIST /D
Dry content	UNIT RATIO D/W	— <u>D</u> W x 100	% RATIO D/W
Ratio *2	UNIT RATIO W/D	<u>W</u> x 100	% RATIO W/D
Gram value	UNI T a	_	g

W: Wet sample mass

D: Dried sample mass

\*1: Factory settings

\*2: When result reaches to 999%, measurement is stopped.

### "Date"

It is printed date and time of the built-in clock in the analyzer. Arrangement of the calendar is the same setting of the built-in clock. Refer to ".6.2 Setting the Clock and Calendar "

If you need to adjust the clock, refer to ".6.2 Setting the Clock and Calendar "

	$\sim$
DATE	2003/08/01
TIME	13: 24: 57
$\sim$	$\frown$

### "Remarks Space"

 $\widehat{}$ 

For instance: This space can use for a comment about samples.



# "Signature Space"




# 11. Connecting to a Computer

- The analyzer can be connected to personal computer using the RS-232C interface.
- The analyzer is the Data Communication Equipment type (DCE).
   Use a straight-through type cable.

The MS-70 and MX-50 have the following standard accessory cable for RS-232C. If it is necessary to connect a cable to the MF-50 and ML-50, purchase the cable of accessory AX-MX-40. If purchasing the RS-232C cable on the market, check the interface connections and type.

RS-232C Cable Included As A Standard Accessory Of The MS-70 and MX-50 Length 2m, straight-through type for modem




- The MS-70 and MX-50 have the standard accessory software "WinCT-Moisture" for Windows. It has the function to make graphs of the change of moisture content in realtime and has an optimum temperature search program that judges heating at an appropriate temperature setting. Refer to "English\Readme.txt" on the CD-ROM for the details.
- The MF-50 has the standard accessory software "WinCT" for Windows. It can transmit data to a computer and can be used to monitor data and to check the measurement condition.
- □ There is the accessory AX-MX-42 of the software "WinCT" for Windows.

# 11.1. RS-232C Serial Interface

## **RS-232C Serial Interface**

3-Z							
	Transmission system	EIA RS-232C					
o	Transmission form	Asynchronous, b	i-directional, half duplex				
	Data format	Baud rate 2	2400bps				
	Data bits	7bits	·				
	Parity	EVEN					
	Stop bit	1bit					
	Code	ASCII					
	Terminator	CR LF (CR: 0Dh	LF: 0Ah)				
	Bit format	, , , , , , , , , , , , , , , , , , ,	,				
			RS-232C				
		MSB 1	-5 V to -15 V				
			+5 V to +15 V				
	Data bits	Cton hit					
	Data bits	└─ Stop bit					
	Start bit	Parity bi	t				
		-					

#### **Pin Connections**



	MX-50 and	MF-50 (DCE)	Direction	Computer (DTE)
Pin No.	Signal Name *2	Description	Direction	Signal Name
1	FG	Frame ground	_	FG
2	RXD	Receive data	$\leftarrow$	TXD
3	TXD	Transmit data	$\rightarrow$	RXD
4	RTS	Ready to send *3	$\leftarrow$	RTS
5	CTS	Clear to send *3	$\rightarrow$	CTS
6	DSR	Data set ready	$\rightarrow$	DSR
7	SG	Signal ground	_	SG
16, 18, 19, 21, 23	Internal use		Do not co	onnect *1
Other	Not used			

\*1: Normal DOS/V cables do not use these terminals.

\*2: Signal names of the analyzer side are the same as the DTE side with TXD and RXD reversed.

\*3: RTS and CTS control are not used. CTS output is HI always.

# 11.2. Output Format

In Case of Format omitted Temperature Data (Function Table 5-d 0)

- The format consists of fifteen characters except the terminator.
- A polarity sign is placed before the data with the leading zeros. If the data is zero, the plus sign is used.
- □ The unit is unit is or unit.
- **□** The position of decimal point and minimum display are changed by models.
- □ Sign of ASCII code
  - CR 0Dh Carriage return
  - 🔄 0Ah Line feed
  - \_ 20h Space

## Sample Mass Format (Gram Display)

ST, +0001.234\_gCRLF

Header Mass data Unit Terminator

Positive Overload Format (Too heavy weighing, e display) OL, +9999999E+19c<sub>R</sub>L<sub>F</sub>

Header <sup>\</sup>Polarity Overload Terminator

Negative Overload Format (Too light weighing, \_\_e display)  $O[L], -999999991 + 19^{C_R}$ 

Header <sup>\\_</sup>Polarity Overload Terminator

## Moisture Content (during weighing or after weighing) In case of the MS-70

ST, +0012. 345 ... %<sup>C</sup>RLF

Header Moisture content Unit Terminator

In case of the MX-50 or MF-50 S T , +00023.45\_%

Header Moisture content Unit Terminator


In case of the ML-50 ST, +000123.4 - 600

Header Moisture content Unit Terminator

### In Case of Format included Temperature Data (Function Table 5-d 1)

The first 3 figures are the temperature data.
 The format consists of nineteen characters except the terminator.

In case of the MS-70



In case of the MX-50 or MF-50

160, ST, +00023.45\_\_%C<sub>R</sub>L<sub>F</sub> Header Moisture content Unit Terminator 160°C at sample pan

In case of the ML-50

1 6 0 , S T , + 0 0 0 1 2 3 . 4 . %<sup>C</sup><sub>R</sub>L<sub>F</sub>

Header Moisture content Unit Terminator 160°C at sample pan

# 11.3. Command

• The analyzer can be controlled by the following commands from the computer. Add a terminator  $C_R L_F$  (0Dh, 0Ah) to each command.

Command	Description
Q	Outputs the current data.
SIR	Outputs data continuously
С	Stops data output by SIR command.
QM	Outputs the data during measurement. (In other mode, QM can not use.)
START	Same as the START key
STOP	Same as the STOP key
RESET	Same as the RESET key
ENTER	Same as the ENTER key
SELECT	Same as the SELECT key
DOWN	Same as the key
UP	Same as the key
PROGRAM	Same as the PROGRAM key

# 12. Data Memory Function


□ The data memory function automatically stores each result when finishing a measurement.

	MS-70 / MX-50	MF-50	ML-50
Maximum number	100 data	50 data	30 data

- The stored data can be output to a printer at one time and can be output to a computer using RsCom and Rskey that are Windows applications stored in the CD-ROM of WinCT-Moisture or WinCT at one time.
- The stored data can be deleted at one time.
- □ When using the data memory function, MEM is displayed.
- □ When displaying <u>full</u>, the function can not store the next data. The function can store new data after deleting the stored data.

### Caution

- When pressing the <u>STOP</u> key during a measurement except manual mode, the result is not stored.
- Set data 1 before measurement, if it is necessary to store each result with data memory function.




# 12.1.1. Preparation

This example selects "store result" at data of the function table.

1. Display the gram unit (of the weighing mode). 0000g SELECT Press and hold 2. Press and hold the SELECT key to enter the CI ad function table. SELECT 3. Press the SELECT key to display data. data 3. Press the SELECT key several times and press ENTER the or the key to display data "1. ₽ Store result "1 data 5. Press the ENTER key to store the new settings. Press the **RESET** key to return to the weighing mode. 5-d MEM | is displayed when the memory function is effective. RESET MEM 0000g 0

# 12.1.2. Output All Data at One Time



6. When deleting is finished, end is displayed.

MEM

Data is cleared

0

0000g

# 13. Calibration

- □ The moisture content is calculated with a ratio of wet weight and dried weight. Therefore, the absolute value of weighing does not influence the calculation of the moisture content, but it is necessary to get precise weighing for GLP, GMP and ISO. Use a 20g mass or a 50g mass to calibrate the weighing sensor.
- When calibrating the weighing sensor, you can output the calibration report adapted to GLP, GMP and ISO.
- □ There is a certified temperature calibrator (accessory AX-MX-43, only for MS-70 and MX-50) to calibrate the pan temperature for precise temperature control.
- When calibrating the temperature, you can output the calibration report adapted to GLP, GMP and ISO.
- □ The analyzer can store an ID number to be used in the calibration report. The number can be used for management and maintenance of the analyzer


# 13.1. Identification Number (ID No.)

I ne ID number consists of the following seven characters.																
0	1	2	З	4	5	6	7	8	9	S	pac	e	-(	hyp	her	า)
0	1	2	S	4	5	6	7	8	9	_						
А	В	С	D	Е	F	G	Н	I.	J	Κ	L	Μ	Ν	0	Ρ	Q
а	b	С	d	е	f	g	Η	i	j	k	Ι	m	Ν	0	р	q
									-							
R	S	Т	U	V	W	Х	Υ	Ζ								
r	S	t	U	V	W	Х	у	Ζ								
	0 0 A a R	0 1 0 1 A B a b	0     1     2       0     1     2       A     B     C       a     b     C       R     S     T	0       1       2       3         0       1       2       3         A       B       C       D         a       b       C       d         R       S       T       U	0       1       2       3       4         0       1       2       3       4         A       B       C       D       E         a       b       C       d       e         R       S       T       U       V	0       1       2       3       4       5         0       1       2       3       4       5         A       B       C       D       E       F         a       b       C       d       e       f         R       S       T       U       V       W	0       1       2       3       4       5       6         0       1       2       3       4       5       6         A       B       C       D       E       F       G         a       b       C       d       e       f       g         R       S       T       U       V       W       X	0       1       2       3       4       5       6       7         0       1       2       3       4       5       6       7         A       B       C       D       E       F       G       H         a       b       C       d       e       f       g       H         R       S       T       U       V       W       X       Y	0       1       2       3       4       5       6       7       8         0       1       2       3       4       5       6       7       8         A       B       C       D       E       F       G       H       1         a       b       C       d       e       f       g       H       i         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9         0       1       2       3       4       5       6       7       8       9         A       B       C       D       E       F       G       H       I       J         a       b       C       d       e       f       g       H       i       j         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9       S         0       1       2       3       4       5       6       7       8       9       S         0       1       2       3       4       5       6       7       8       9       S         A       B       C       D       E       F       G       H       I       J       K         a       b       C       d       e       f       g       H       i       j       k         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9       Space         0       1       2       3       4       5       6       7       8       9         A       B       C       D       E       F       G       H       I       J       K       L         a       b       C       d       e       f       g       H       i       j       k       I         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9       Space         0       1       2       3       4       5       6       7       8       9         A       B       C       D       E       F       G       H       I       J       K       L       M         a       b       C       d       e       f       g       H       i       j       k       I       m         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9       Space       -(         0       1       2       3       4       5       6       7       8       9       -(         A       B       C       D       E       F       G       H       I       J       K       L       M       N         a       b       C       d       e       f       g       H       i       j       k       I       m       N         R       S       T       U       V       W       X       Y       Z	0       1       2       3       4       5       6       7       8       9       Space       -(hyp         0       1       2       3       4       5       6       7       8       9	0       1       2       3       4       5       6       7       8       9       Space       -(hypher         0       1       2       3       4       5       6       7       8       9          A       B       C       D       E       F       G       H       I       J       K       L       M       N       O       P         a       b       C       d       e       f       g       H       i       j       k       I       m       N       O       P         a       b       C       d       e       f       g       H       i       j       k       I       m       N       o       p         R       S       T       U       V       W       X       Y       Z       V

The ID number consists of the following seven characters

# 13.1.1. Setting the ID Number

- 1. Turn on the analyzer. The gram unit (of weighing mode) is displayed.
- 2. Press and hold the SELECT key to enter the function table. Then CI adj is displayed.
- 3. Press the SELECT key to display id.
- 4. Press the ENTER key.
- 5. Set the ID number using the following keys. Example: I ab-123 SELECT key ... Selects a figure. ENTER key..... Stores the ID No. and proceeds to step 6.
- 6. Press the **RESET** key to return to the weighing mode.




# 13.2. Calibration of the Weighting Sensor

- □ A standard mass of 20g or 50g can be used for the calibration
- □ A 20g standard mass (AX-MX-41) is recommend.

#### Caution

- Avoid vibration and drafts that affect the calibration. If affected, the analyzer may be unable to calibrate the weighing sensor.
- Use a 20g mass for the calibration, because the height between the weighing pan and glass-housing is 26 mm. If a tall mass is used, open the glass-housing and avoid external influence.

# 13.2.1. Operation



# Calibration Report Example for the Weighing Sensor Adapted to GLP, GMP and ISO

Device	Parame	ter	Description
	Interval	pU5e 1 *1	Approx. two seconds interval in each line.
Analyzer	Output format	info 1	Calibration report is printed at "Calibration of the
	adapted to GLP,	or	Weighting Sensor" and "Calibration of Drying
	GMP and ISO	info 2	Temperature".
AD-8121B	MODE	3	Dump print (Received data is printed as it is)


Preset the following parameters to print data to AD-8121B

\*1: Factory settings


	A & D	Manufacture
MODEL	MX-50	Model
S/N	K1234567	Serial number
ID	LAB-123	ID number
DATE	2004/09/30	Date
TIME	13: 57: 24	Time
CALI BI	WEI GHT	Calibration type
CAL. WI	20. 000 g	Calibration mass
SI GNA	TURE	
		Signature

# 13.3. Calibration of Drying Temperature (for MS-70 and MX-50)

- The temperature calibrator (accessory AX-MX-43) adjusts the drying temperature on the pan. Put the sensor on the pan and input measurement data at 100°C and 160°C.
- Each adjustment needs fifteen minutes. The buzzer sounds at the end.
- <u>t-Up</u> is displayed after no adjustment for five minutes during the operation and calibration is stopped. Press any key to return to weighing mode.
- Refer to the instruction manual of the certified temperature calibrator (accessory AX-MX-43).



## 13.3.1. Operation



- 10. After fifteen minutes, the buzzer sounds and the display blinks <u>160°C</u>. Adjust the blinking value to the thermometer value using the ↓ or ↑ key. (Example: 162°C)
- 11. Press the ENTER key to store the new data, to finish the adjustment and to return to the weighing mode.

If the report for GLP, GMP and ISO is output, glp is displayed. Output condition is selected in the function table.


When the heater cover is opened during measurement or the <u>STOP</u> key is pressed, calibration is stopped and the analyzer displays the weighing mode.


# Calibration Report Example for Temperature Sensor Adapted to GLP, GMP and ISO Preset the following parameters to print data to AD-8121B

Device	Parame	eter	Description
	Interval	pU5e 1 * <b>1</b>	Approx. two seconds interval in each line.
Analyzer	Output format info 1		Calibration report is printed at "Calibration of the
	adapted to GLP,	or	Weighting Sensor" and "Calibration of Drying
	GMP and ISO	info 2	Temperature".
AD-8121B	MODE	3	Dump print (Received data is printed as it is)

\*1: Factory settings

	ŀ	4 & [	Manufacture
MODEL	Ν	MX-50	Dimme Model
S/N	K123	34567	/ Serial number
ID	LAE	3-123	3 ID number
DATE	2004/0	09/30	D Date
TIME	12: 3	34: 56	5 Time
CALI B			Collibration turns
	TEMPERA	ATURE	E Calibration type
TARGE	T AC	CTUAL	-
100	C c	97 (	c 100°C target value measurement value
160	C 16	62 (	c 160°C target value measurement value
SI GNA	TURE		
			Signature





# 14. Function Table

The function table can store the following parameters to control the analyzer.

Details of the F	unction	able	e				
Item and Display Symbol			am- :er		Description		
			Set date and time for the built-in clock.				
Clock	CI adj	Ref	er to	6.2. Setting the	clock and calendar"		
De sins el maint	alua	0	*1	Dot " . "		f data	
Decimal point	dp	1		Comma " , "	Select decimal point c	r data.	
		0	*1	Key mode	Data is output by the	ENTER key	
Data output	nrt	1		Auto print mode	Data is output after m	easurement.	
mode	prt	2		Straam mada	Data is output continu	ously during	
		2		Stream mode	measurement.		
Data memory	data	0	*1	Not used.			
function	uata	1		Data is stored at	each measurement		
Form selection	5-d	0	*1	Moisture content	is output.		
FOITT SELECTION	5-u	1		Moisture content	and temperature are o	utput.*2	
Interval	pU5e	0		Continuous outpu	t		
IIILEIVAI	puse	1	*1	Output with appro	x. two seconds interval i	n each line.	
		0	*1	Not used			
	apted to P, GMP and info			To output (print) i	tems with "analyzer		
Output format				1	information", "measurement program",		
adapted to				"measurement da	ata" and ""signature	Output of	
GLP, GMP and		THIO			space" at one tim	ne. *3	calibration
ISO		То с		tems specified from	report. *5		
		-		ation", "measurement			
				program" and "si	gnature space". *4		
ID number	id	Set	ID r	number. Used for t	he calibration report.		
Factory settings	Clr	Res	sets	the analyzer to the	e factory settings.		

# Details of the Function Table

\*1: Factory settings


\*2: Use a computer because the AD-8121B printer can not print this correctly. RsTemp and RsFig contained in the software "WinCT-Moisture" that is the standard accessory of the MS-70 and MX-50 can not output this correctly.

\*3: Refer to "10.1.1. Example To Print The Whole Data At One Time".

\*4: Refer to "10.1.2. Example To Print Selected Items".


\*5: Calibration report is outputted in "Calibration of the Weighting Sensor" and "Calibration of Drying Temperature".

# 14.1.1. Operation



# 15. Maintenance


- Turn off the power switch and remove power cord during maintenance.
- Cool down all parts of the analyzer before maintenance.
- □ Pan support, sample pan and breeze break ring can be removed.
- Clean the analyzer with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not use organic solvents to clean the analyzer.
- Dry the parts and reassemble them. Refer to "3. Precautions" and "6.1. Installing the Analyzer"
- Use the original packing material and box for transportation.




Example

# 15.1. Cleaning the Heater Unit

- Clean the glass-housing when it is stained (not clear) to maintain the drying performance.
- The glass-housing can be removed by removing two screws.
- Remove fingerprints from the halogen lamp to keep its life.
- Do not touch to reflective surface of the metal reflector.
   If the surface is touched, it may be the cause of a drying temperature error.
- Do not touch the temperature sensor that is at the side of halogen lamp. If the surface is touched, it may be the cause of a drying temperature error.





# 15.2. Replacement of the Halogen Lamp

 Replace the halogen lamp, when the drying time is excessive or the lamp is defective. Use the halogen lamp of accessory AX-MX-34-120V or AX-MX-34-240V that is adapted to your local voltage. The life of the halogen lamp is approximately 5000 hours.

### Caution

- Remove power cord before replacement. If the power cord is not removed during lamp replacement, it may cause receiving an electric shock.
- Read the power supply voltage label on the back of the heater cover and confirm that the rated voltage of the halogen lamp is correct for your power supply voltage.

Voltage Label	The Rated Voltage of the Halogen Lamp	Accessory number
100 - 120 V	AC 120 V	AX-MX-34-120V
200 - 240 V	AC 240 V	AX-MX-34-240V

Do not drop, throw or crack the halogen lamp. Broken glass may cause an injury.

Screw

Halogen lamp

Connector

Read rated

voltage.

Glass-housing

Wire

000

Screw

Holder

Hook


- Clean the surface of the halogen lamp. If there is a stain or fingerprint, it may shorten life of the halogen lamp. Do not touch the lamp directly.
- Dispose of a used halogen lamp that keeps its shape. If it is broken, glass may spread and cause injury.
- We recommend that you replace the halogen lamp, when it exceeds the rated life.
- Affix the lamp wire to the hook so that the lamp wire does not touch the glass-housing and heater cover.
- 1. Turn off the power switch and remove power cord.

There is downward projection.

Heater Unit

Hook

- 2. Check rated voltage of the halogen lamp that is printed around the holder.
- 3. Check that the lamp is cool.
- 4. Remove the two screws holding the glass-housing.
- 5. Remove halogen lamp.
- 6. Install the new halogen lamp so that there is downward projection of the heat and light.
- 7. Affix the lamp wire to the hook.
- Affix the glass-housing with the two screws.
   Do not pinch the wire between the glass housing and lid.



# 15.3. Factory Settings

This function can set the following parameters to factory settings.

- All measurement programs
- All results stored in memory function.
- All parameters of the function table
- □ ID number is reset to 0000000.
- Order of calendar and date.


# 15.3.1. Operation

- 1. Turn on the analyzer. The gram unit (of the weighing mode) is displayed.
- 2. Press and hold the <u>SELECT</u> key to enter the function table.
- 3. Press the SELECT key to display CIr.
- 4. Press the ENTER key to enter the item.
- 5. Press the I or 1 key to display CIr go.

### Caution

If pressing the ENTER key with CIr hb and pressing the RESET key, operation is canceled.

- 6. Press the ENTER key to reset. And end is displayed.
- 7. Press the **RESET** key to return to the weighing mode.





# 15.4. Troubleshooting

- 1 . In the Case that Proper Results are not be Obtained.
  - □ Use the self-check function. Refer to 9.1.Self-Check Function .
  - Check repeatability. (Weigh the same mass several times in the weighing mode.) A taller mass may touch the glass-housing. Use a short mass if possible. If a tall 50g mass is used, open the heater cover and avoid external influence.
  - The height from sample pan to glass-housing is 26 mm.
  - Check whether the test sample can be measured correctly.
  - Avoid the breeze from an air conditioner and vibration.
  - Check sample condition. Refer to 6.3. Proper Operation for Precision Measurement
  - □ Check measurement procedure and pre-heating process. Refer to 6.3.Proper Operation for Precision Measurement
- 2 . In Case that the Lamp does not Light or it takes Too Long to Reach the Drying Temperature.
  - It requires six seconds to light the halogen lamp using the START key.
  - When the heater cover is opened, power is not supplied to the halogen lamp.
  - When an overheat has occurred, power is not supplied to the halogen lamp until the halogen lamp becomes cool.
  - Check the rated voltage of the halogen lamp that is printed around the holder.
  - Read the power supply voltage label on the back of the heater cover and confirm that the rated voltage of the halogen lamp is correct for your power supply voltage.

Voltage Label	Power Supply Voltage	The Rated Voltage of the Halogen Lamp	Accessory number
100 - 120 V	AC 100 V to AC 120 V	AC 120 V	AX-MX-34-120V
200V - 240 V	AC 200V to AC 240 V	AC 240 V	AX-MX-34-240V

- Is a fuse blown? Check the fuses after removing the power cord. Check the rated value and put new fuses into the correct holders.
- Do you measure a lower drying temperature after a high drying temperature? If the lamp is hotter than the drying temperature, the measurement can not be started.
- Check that the sample pan is cool.
- Other cases, the halogen lamp may be defective. Replace with a new halogen lamp. Refer to "15.2. Replacement of the Halogen Lamp".





Halogen lamp Read rated voltage

# 15.5. Error Message


CH no	Internal Error An internal error indicated by the result of the self-check function. If repair is needed, contact the local A&D dealer.
Cl pf	<b>Clock Battery Error</b> Press any key and input the date and time. Refer to "6.2. Setting the Clock and Calendar ".
CI err	<b>Clock Error</b> Contact the local A&D dealer to repair the analyzer.
CI o5e	Heater Cover Error The heater cover is opened when starting self-check function. If it is closed, the self-check function is started.
error0	Internal Error Turn the power switch off and then on . Check the frequency of the power supply. Contact the local A&D dealer to repair the analyzer, if the error is not cleared.
error3 error8 error9	IC Error Contact the local A&D dealer to repair the analyzer.
Ht err	<b>Temperature Control Error</b> Contact the local A&D dealer to repair the analyzer, if an error is not cleared when turning the power switch off for more than a half hour and rechecking it.
t-Up	<b>Time Error at Temperature Calibration</b> There is no key operation for five minutes during temperature calibration. If pressing any key, the weighing mode is displayed.
е	<b>Positive Overload, Overweight</b> The sample has exceeded the weighing capacity. If the weighing sample pan is empty and this error is displayed, contact the local A&D dealer to repair the analyzer.
-e	Negative Overload, Sample Pan Error The weight value is too light. Check the pan, pan support and press the <u>RESET</u> key. Calibrate the weighing sensor. If an error can be not cleared, contact the local A&D dealer to repair the analyzer.
mem fUI	Full Memory The number of results stored in memory has reached the upper limit. Clear the data to store the new results. Refer to "12. Data Memory Function".

# 16. Specifications

		MS-70	MX-50	MF-50	ML-50
Meas	surement method	400 W	halogen lamp, the	ermogravimetric a	analysis
-	ng temperature e at sample pan		50°C to 200°C (	1°C increments)	
Heat	ing pattern		ard drying, Ramp o drying, Quick dr		Standard drying, Quick drying
Tem	perature calibration		ry AX-MX-43	-	
Sam	ple weight range	0.1 g to 71 g		0.1 g to 51 g	
Accu	racy: Repeatability	of measurement, (	(Standard deviatio	on)	
M	pisture content *1				
	over 5 g sample	0.01 %	0.02 %	0.05 %	0.1 %
	over 1 g sample	0.05 %	0.1 %	0.2 %	0.5 %
	eighing mode	0.0005 g	0.001 g	0.002 g	0.005 g
Minir	num reading	1	1		
Mo	oisture content	0.001 %, 0.01 %, 0.1 %	0.01 %, 0.1 %	0.05%, 0.1 %, 1 %	0.1%, 1 %
14/	eighing mode	0.0001 g	0.001g	0.002g	0.002g
	surement programs	0.000 T g	0.001g	0.0029	0.002g
	Standard mode	ACCURACY an termination value	nd % display. N e, measurement i	value is autom When drying ra s automatically co	te reaches the
mode	Quick mode	Standard drying, Ramp drying, Step dryingStandard dryingSample weight and termination value is automatically set witACCURACY and % display. When drying rate reaches thtermination value, measurement is automatically completed. (*2)Quick drying			atically set with te reaches the
Analysis mode	Automatic mode	measurement is	rate is less t automatically cor Ramp drying, Ste		mination value, Standard drying
A	Timer mode	After heating automatically sto	for the preset opped. (1min. to 4	drying time, 80 min.)	measurement is
	Manual mode	When pressing the result is deci	ded.	me, measuremen	
M	easurement unit	Standard drying, Ramp drying, Step dryingStandard dryingMoisture content (Wet-base)Moisture content (Dry-base, Atro)Dry contentRatio			Standard drying
		Weight (g)		40	<b>–</b> (
	umber of memory		sets	10 sets	5 sets
	memory function	100 r	esults	50 results	30 results
funct			RS-232C se	erial interface	
	ication software for dows (CD-ROM)	WinCT-Moisture	Analyzing utility	WinCT Communication software	

	MS-70	MX-50	MF-50	ML-50
Operation environment	5°C to 40°C (4	41°F to 104°F), 85	5%RH or less (no	condensation)
Sample pan		φ85	mm	
Power source, Maximum current (r.m.s), Maximum consumption	Please conf		proximately 400W lyzer is correct fe ceptacle type.	<i>)</i> or your local
External dimensions	215(W) x 320	(D) x 173(H)mm,	8.46(W) x 12.60(I	D) x 6.81(H)in.
Mass (Net weight)	Ар	proximately 6kg (	without accessori	es)

- \*1: After preheating the analyzer, the data can be obtained with approximately 5 g test sample (Sodium tartrate dihydrate) in standard mode (MID.), standard drying, 160 °C
- \*2: When change of moisture content per one minute reaches the preset termination value, the measurement is completed.



# 16.2. Accessories and Peripheral Equipment


#### Accessories

Name	Order number
Sample pan (	AX-MX-31
Glass fiber sheet, φ70 mm, (Filter paper, 100 sheets) Use for high surface tension liquid sample.	AX-MX-32-1
Glass fiber sheet, φ78 mm, ( Glass paper, 100 sheets) The same sheet as accessory. Use liquid sample.	AX-MX-32-2
Test sample (Sodium tartrate dihydrate, 30gx12 pcs)	AX-MX-33
Halogen lamp for AC 100V to 120 V	AX-MX-34-120V
Halogen lamp for AC 200V to 240 V	AX-MX-34-240V
Pan handle ( 2 pcs)	AX-MX-35
Tweezers (2 pcs)	AX-MX-36
Spoon (2 pcs)	AX-MX-37
Display cover (5 pcs)	AX-MX-38
Dust cover	AX-MX-39
RS-232C cable (2m, 25 pins - 9 pins)	AX-MX-40
Calibration mass (20g, equivalent to OIML class F1)	AX-MX-41
WinCT-Moisture (CD-ROM: Application software for Windows)	AX-MX-42
Certified Temperature calibrator (only for MS-70 and MX-50)	AX-MX-43

### Peripheral equipment

AD-8121B Dot matrix compact printer

Function:Statistical function, interval printing, chart printing,<br/>5x7 dot, height 2.5mm/01.in., 16 characters/linePower source:AC adapter or alkaline batteries



# 17. Index

%/min 18, 21, 26	i, 28
O, ENTER key	- 13
, PROGRAM key	- 13
, RESET key	- 13
, SELECT key	
(stop), START key	
, STOP key	
	- 13
Standard drying 13, 29	
$\bigtriangledown$ $\bigtriangledown$ Quick drying	
<ul> <li>✓ ⊂ Ramp drying 13, 32</li> </ul>	
<ul> <li>✓ ✓ Step drying</li> <li>✓ Is, 62</li> </ul>	
Operation state indicator	- 12
Level indicator	- 12
ACCURACY 18, 21, 25	5, 26
AD-8121B 43	8, 69
Ambient condition	5
Analysis mode8	5, 25
Analyzing mode 25	
Auto print mode	- 60
Automatic mode8, 25, 27, 28, 36	
Baud rate	- 50
Breeze break ring6, 10, 11	
Bubble spirit level 10	
Calendar	
Calibration	- 55
Calibration report 57	
Cancel key	, 00 - 13
СН	- 41
СН по	
СН ра55	
Character	
Cl pf	
Cl adj	- 60
Cl err	- 66
Cl o5e 41	
Clock 15	
Cl r 54	
Clr go	
Comma	- 60
Command	- 52
Continuous measurement	
	10

CR				-51
CTS				-50
data			-53.	60
Data bits				
Data memory				
Data memory function				-00
Data memory function				-60
Data output mode				-60
Decimal point				-60
Display				-12
Display cover				-11
dmy				-15
dmy Dot				-60
dp				60
				-00
Dried sample mass				-28
Dry content				-28
Heating pattern		8,		
Drying rate				-25
Drying temperature25,	27,	33.	35.	58
DSR				
Dust cover				.11
e				
-e				
Earth terminal				-14
ENTER key				-13
error0				-66
error3				-66
error8				
error9				
Factory settings				
FG				-00
full				
Fuse			-10,	11
Glass fiber sheet				
Glass-housing	6,	10,	11,	63
gl p				
GLP	-43	56	59	60
GMP				
	-40,	50,	59,	200
Gram value				-28
Grip				
Halogen lamp5, 8, 10,				
Header				
Heater cover				-10
HI		-18.	21.	26
Ht err			·	-66
/				
i d				
ID number				
Indicators				
info				-60

ISO 43, 56, 59, 60	۱
Key mode 60	, )
Keys 12	>
Leveling foot 10, 14	ŀ
LF 51 li5t 45	
LO 18, 21, 26	5
Manual mode8, 25, 27, 36, 38	5
Mass 56, 65 mdy 15	5
mdy 15	)
Measurement program 25	)
MEM 24, 53, 66 MID 18, 21, 26	) :
MID:	, {
MOIST /W 28	
Moisture content 28, 55, 60	)
out 54	ł
Output format 51, 60	)
Pan handle 10, 11, 14	ŀ
Pan support 10, 11, 14	ŀ
Parity 50	)
Polarity 51	
Power cord 10, 11	
Power input 10	
Power supply voltage label 5, 14, 65 Power switch 10, 14	) I
Pre-heating process 16	
Printer 43, 69	י ג
PROG8, 24	
PROGRAM key 13	
prt 60	)
quc 25	
Quick drying 27, 36, 38	
Quick mode8, 25, 27, 36, 38	
Ramp drying8, 27, 32, 34, 36, 38	5
Ratio 28	
RATIO D/W 28	
RATIO W/D 28	
Reference card 10	
Repeatability 16 Report 57, 59	
RESET key 13	
RS-232C 10, 49, 50	
	•

RTS		50
RXD		
Sample mass		25
Sample pan 6,	10,	11
5-d	51,	60
SELECT key		13
SG		50
SG		45
Sodium tartrate dihydrate		42
Spoon		11
Standard accessories	10,	11
Standard drying 8, 27, 29, 36,	38,	42
Standard mode 8, 25, 27,	36,	38
START key		13
START key 5td	13,	25
Step drying 8, 27,		
Stop bit		50
STOP key		13
Stream mode		
t-Cal		58
Temperature		- 5
Temperature sensor		58
Terminator	50,	51
Test sample	10,	42
Thermogravimetric analysis		- 9
Thermometer		58
Timer mode 8, 25, 27, 28,	36,	38
Test sample		11
t-Up		66
Tweezers		
TXD		
U-a		
U-m	-,	-
Unit	28,	51
U-t		
Weighing sensor	55,	56
Wet sample mass		28
WinCT	- 8,	49
WinCT-Moisture		
<u>y</u> md		
Zero display		13

# MEMO




### A&D Company, Limited

3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013 JAPAN Telephone: [81] (3) 5391-6132 Fax: [81] (3) 5391-6148

#### **A&D ENGINEERING, INC.**

1555, McCandless Drive, Milpitas, CA. 95035 U.S.A. Telephone: [1] (408) 263-5333 Fax: [1] (408)263-0119

#### A&D INSTRUMENTS LTD.

Unit 24/26 Blacklands Way, Abingdon Business Park, Abingdon, Oxon OX14 1DY United Kingdom Telephone: [44] (1235) 550420 Fax: [44] (1235) 550485

#### <German Scales Office>

Große Straße 13 b 22926 Ahrensburg GERMANY Telephone: [49] (0) 4102 459230 Fax: [49] (0) 4102 459231

#### A&D MERCURY PTY. LTD.

32 Dew Street, Thebarton, South Australia 5031 AUSTRALIA Telephone: [61] (8) 8301-8100 Fax: [61] (8) 8352-7409

#### **A&D KOREA Limited**

8th Floor, Manhattan Bldg. 36-2 Yoido-dong, Youngdeungpo-ku, Seoul, KOREA Telephone: [82] (2) 780-4101 Fax: [82] (2) 782-4280

MS-70 / MX-50 / MF-50 / ML-50